PRINTED: 11/15/2012 FORM APPROVED

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING  01		(X3) DATE SURVEY COMPLETED	
000092			B. WING		11/09/2012		
			STREET ADD	ADDRESS, CITY, STATE, ZIP CODE			
CI ENDDOOK DELIADII ITATION & SKII I ED NI IDSING				RNELL AVE AYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	(EACH CORRECTIVE ACTION SHOUL	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE ROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	
K 000	INITIAL COMMENTS			K 000			
	A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health.						
	Survey Date: 11/09/12						
	Facility Number: 000092 Provider Number: 155176 AIM Number: 100266090						
	Surveyor: Robert Sutton, Life Safety Code Specialist Trainee						
	At this Quality Assurance Walk-thru survey, Glenbrook Rehabilitation & Skilled Nursing Center was found in compliance with 410 IAC 16.2-3.1-19(ff).						
	This one story facility with a basement was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, and areas open to the corridors with battery operated smoke detectors in the resident rooms. The facility has a capacity of 90 and had a census of 73 at the time of this visit.						
	<u>-</u>	mpliance with state law verage and smoke dete					
		ents have customary ac all areas providing faci ered.					
		bert Booher, Life Safet cal Surveyor on 11/14/					
			l				

Indiana State Department of Health

TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE